

APPENDIX 1: PHOTOGRAPHS OF THE KHAYELITSHA ABLUTION BLOCKS

Khayelitsha Ablution Blocks in 2003



Khayelitsha Ablution Blocks were managed by a contractor in 2003. The facilities were fully operational and safe to use.

Khayelitsha Ablution Blocks 2006



In 2006, the Khayelitsha Ablution Blocks had fallen into disrepair and were an environmental health hazard to the surrounding community before they were refurbished.



Incidents of vandalism resulted in significant damage to the ablution blocks